



Installing the Snap-in Cap in the SLX Port, Item 22950

1. At the front of the SLX Port line up the snap-in plug with the opening in the port. The plug may then be tapped into place using a mallet or hammer and a block of wood. The plug may also be stepped on to snap it in to place.

